

S411



#401445
Double joint cardan DJC set (2)

Modification:

when mounting the DJC set, the shaft may touch the inside of the c-hub. To prevent binding its best to cut a little bit of material from the inside as indicated in the image.

The mould of the c-hubs will be modified in the meantime.



Part-list

Double joint cardan DJC set (2)(#401445)

401446 Driveshaft DJC (2)

401447 Weelaxle DJC (2)

401448 Coupler DJC (2)

401449 Insert DJC (4)

401450 Pin revision set DJC (2+2)